


B.A. THREADS

Application : B.A. threads are used for fine fastening, especially in instruments.



SPECIFICATION : Basic Dimensions : B.S.93-1951.
Gauging Practice : B.S 919 Part II - 2007

MANUFACTURING RANGE

B.A. No.	Pitch in mm	Type of Thread Gauges used			
2	0.81	Thread Plug Gauges Tolerance class : • Normal (N) • Close (C)	Thread Ring Gauges Tolerance class : • Normal (N) • Close (C)	Check Plug Gauges to check NEW Ring Gauges. Tolerance class : • Normal (N) • Close (C)	Wear Check Plug Gauges to check/ calibrate used Ring Gauges. Tolerance class : • Normal (N) • Close (C)
3	0.73				
4	0.66				
5	0.59				
6	0.53				
7	0.48				